


Intellibot Robotics new Reporting Package is the accountability tool that environmental service professionals have been seeking! Owners and managers can finally track the usage of their cleaning equipment, see exactly who is using the equipment and see what areas have been cleaned and when.



Using a simple touchscreen, authorized personnel can access a series of informative and useful reports. The interface is intuitive and easy to use, with icons and interactive menus to guide the user. Reports can also be e-mailed from the robot to a selected account on a predetermined schedule, or wirelessly uploaded to the secure customer portal on the Intellibot Website*.

By accurately tracking when and where the robot was used, and who was operating it, building owners and crew leaders can more effectively monitor and schedule its usage. Proper implementation maximizes a robot's return on investment and ensures that operators are fully utilizing the power the GEN-X.

1. Information Screen

To access reports, the user first calls up the Information Screen. This screen presents an overall snapshot of the robot's operation to date. Total usage hours are displayed, divided into manual, robotic and idle time. Data is given for the last time the robot was powered up and the last time the robot was run.

| INFO | | 11:51:25 05 Nov 07 |
|------------------------|----------------------|-----------------------|
| Usage Hours | | |
| Robotic Cleaning: | 122:08 | |
| Manual Cleaning: | 6:06 | |
| Idle: | 22:50 | |
| Total: | 151:05 | |
| History | | |
| Last Run: | 29 Oct 07 | 15:30 |
| Last Power On: | 05 Nov 07 | 12:56 |
| Installed: | 22 Sep 07 | 09:58 |
| Cleaning Report | Safety Report | Machine Report |
| | | MORE ▶ |

* Subject to technical requirements and permissions at site.

2. Cleaning Report

The Cleaning Report begins with an overall summary of cleaning that has been performed. Users can quickly scan through the last few days or weeks and ensure that cleaning is being done according to schedule. The details of any given day can be called up in more detail, and the results of any individual map from that day can also be displayed.

| CLEANING SUMMARY | | | | | 11:52:25 05 Nov 07 |
|------------------|---------|--------------------|----------------|-------------|-----------------------|
| Date | Robotic | Manual | Idle | Total | |
| 05 Nov 07 | -- | 0:00 | 0:02 | 0:03 | |
| 02 Nov 07 | -- | 0:01 | 3:28 | 3:30 | |
| 30 Oct 07 | -- | -- | 1:19 | 1:19 | |
| 29 Oct 07 | ⚠ | 3:53 | 0:02 | 3:55 | |
| 25 Oct 07 | | 0:00 | -- | 0:00 | |
| 24 Oct 07 | ⚠ | 3:41 | 0:02 | 3:44 | |
| 22 Oct 07 | ⚠ | 0:05 | 0:01 | 0:07 | |
| 19 Oct 07 | ⚠ | 8:37 | 0:19 | 2:36 | 11:33 |
| Scroll Up | | Scroll Down | Details | Done | |

| CLEANING DETAILS | | | | | 11:54:04 05 Nov 07 |
|------------------|----------|--------------------|--------------------|-------------|-----------------------|
| Date | Robotic | Manual | Idle | Total | |
| 19 Oct 07 | 8:37 | 0:19 | 2:36 | 11:33 | |
| Time | Duration | Mode/Map | Operator | | |
| 16:43 | 0:00 | Manual | Intellibot Quality | | |
| 14:07 | 2:36 | Idle | Intellibot Quality | | |
| 14:06 | 0:00 | Manual | Intellibot Quality | | |
| 12:54 | 1:11 | ⚠ @L | Intellibot Quality | | |
| 12:54 | 0:00 | Manual | Intellibot Quality | | |
| 12:27 | 0:26 | ⚠ @L | Intellibot Quality | | |
| Scroll Up | | Scroll Down | Results | Done | |

| CLEANING RESULTS | | 11:58:01 05 Nov 07 |
|--|-----------|-----------------------|
| Mode/Map: Warehouse A | | |
| End Time: | 19 Oct 07 | 14:06 |
| Start Time: | 19 Oct 07 | 08:04 |
| Duration: | 4:15 | |
| Operator: Wayne O'Brien | | |
| Results | | |
| Cleaning operation completed successfully. | | |
| | | Done |

GEN-X

3. Safety Report

The Safety Report displays all instances when the robot's safety sensors were triggered and any time that the Emergency Stop Button was pressed. The Safety Report is helpful in identifying any possible trouble areas within a building as well as possible misuse or abuse of the machine during operation.

| SAFETY | | 12:52:49 05 Nov 07 |
|---------------------|-------------|-----------------------|
| Component | Hits | |
| Left Front Bumper | 7 | |
| Center Front Bumper | 1 | |
| Right Front Bumper | 127 | |
| Right Rear Bumper | 62 | |
| Left Rear Bumper | 75 | |
| Left Floor Sensor | 0 | |
| Right Floor Sensor | 18 | |
| Left Shield | 3 | |
| Scroll Up | Scroll Down | Unlock Back |

4. Machine Report

The Machine Report displays the number of cycles and total usage time that critical components of the robot have accumulated. This information is very useful for scheduling preventive maintenance, therefore avoiding unwanted down time due to component failure. Intellibot service technicians also use this report to identify any areas that may require attention during scheduled service calls.

| MACHINE | | | 12:55:52 05 Nov 07 |
|---------------------|-------------|----------------|-----------------------|
| Component | Cycles | Usage Time | |
| Vacuum 1 | 97 | 19:10 | |
| Vacuum 2 | 90 | 12:12 | |
| Brush Head Actuator | 374 | 18:18 | |
| Brush Motor | 1240 | 17:07 | |
| Side Broom Motor | 1240 | 17:07 | |
| Pager | 85 | 0:10 | |
| Scroll Up | Scroll Down | Unlock Back | |

To learn more about Intellibot's Reporting Package and our full line of GEN-X Intelligent Floor Care Robots, visit our website at: www.intellibotrobotics.com or contact us at 1-800-297-0391.



GEN-X Scrubber



GEN-X Sweeper/Scrubber



GEN-X Vacuum